



PROJECT PROFILE

PROJECT: Farmhouse - External Refurbishment
LOCATION: United Kingdom

THE PROBLEM

The external rendering on this 19th century farmhouse had been replaced, but had suffered shrinkage and cracking as the newly applied render cured.

Conventional masonry coatings would not allow for this shrinkage and movement.



THE SOLUTION



The deeper cracks were filled using traditional methods.

The whole exterior was then primed using Poly-Tech FB Primer. Hairline cracks and previously filled cracks were bridged using Poly-tech Reinforcing. Two coats of Poly-Tech FP were then applied by brush and roller.

The client is extremely pleased with the result and the value of the property has been enhanced.