



PROJECT PROFILE

PROJECT: External Walls - Church
LOCATION: United Kingdom

THE PROBLEM

The external walls of this church were starting to deteriorate.

The stonework had discoloured badly and erosion and carbonisation was starting to occur.

A system was required that would protect the external surface from further deterioration.



THE SOLUTION



The external walls were first power washed to leave a clean and dry surface and remove any carbonisation that had developed.

Wall-Tech LW was then used to rebuild damaged lintels and surrounds.

The entire external surface of the church was then coated with Aqua-Tech WP. This has provided a clean and totally water repellent surface.