



PROJECT PROFILE

PROJECT: Handrail Refurbishment
LOCATION: Singapore

THE PROBLEM

The balustrading and hand rails within the Somerset MRT Station in Singapore were in poor condition with loose paint and paint failure causing an unsightly appearance throughout the station.



THE SOLUTION



The Thortex solution to this problem involved thorough abrasion to remove all loose paint followed by the application of Uni-Tech GP Primer and Uni-Tech UV as a top coat.

The Uni-Tech GP Primer provided excellent adhesion to the paint and to the exposed GRP surface.