



www.thortex.co.uk

PROJECT PROFILE

PROJECT: Hotel Roof Refurbishment
LOCATION: Portugal

THE PROBLEM

The roof of this Sheraton Hotel had deteriorated over the years and was in need of repair.

Immediate repair and long-term protection was required to ensure that there was no disruption to the busy hotel below.



THE SOLUTION



The main roof area was prepared and primed with Poly-Tech BP Primer prior to the application of two coats of our universal roof protection system Poly-Tech.

The structural steelwork supporting the roof was patch primed with Corro-Tech GP followed by one coat of Uni-Tech GP Primer and then a topcoat of Uni-Tech UV.

The areas of the roof, which are subject to foot traffic, were treated with Floor-Tech FB Primer followed by Floor-Tech FB. A topcoat of Floor-Tech PU was then applied.

The end result, as seen in the photograph, is testament to the high quality and performance capability of Thortex specialist coatings and repair products.