



PROJECT PROFILE

PROJECT: Wooden Floor Refurbishment

LOCATION: United Kingdom

THE PROBLEM

The floor in this room houses a water wash spray booth. Constant splashing from the booth resulted in the wood blocks around the booth being permanently wet, causing them to become loose and eventually lift.

The rest of the floor was extremely dirty and in need of upgrading.



THE SOLUTION



Damaged blocks around the booth were removed and filled in with the Floor-Tech RS Screed. This was then primed and coated with the Floor-Tech HB system.

The remaining wood block floor was cleaned and damaged areas repaired with Timba-Tech. Three coats of Floor-tech CS were then applied.