



PROJECT PROFILE

PROJECT: Protection Of Metal Storage Tanks
LOCATION: Latvia

THE PROBLEM

Bulk storage tanks operated by the company, Rudas Latvia, were severely damaged by corrosion.

The corrosion was so bad that the actual structural integrity of the tanks was threatened and immediate repairs were required to prolong the service life of the tanks in question.



THE SOLUTION



After careful consideration and discussions with our distributor - Ad Rem in Riga, the tanks were dismantled and were blasted to remove corrosion and all other surface contamination. Uni-Tech MC Primer followed by Uni-Tech UV was then applied to the entire surface by spray application. Two coats of Uni-Tech UV were applied to provide long term protection.

Rudas Latvia were delighted by the application because the corrosion problem had been solved and the tanks were as good as new from an appearance and performance point of view.