



PROJECT PROFILE

PROJECT: Swimming Pool Ductwork

LOCATION: United Kingdom

THE PROBLEM

A leading hotel group had instigated a major refurbishment of one of their holiday camp swimming pools.

A suitable finish was required for the protection of galvanised ductwork.

The selected finish had to withstand attack from high humidity and chlorine internally and be aesthetically pleasing externally.



THE SOLUTION



Both internal and external surfaces received one coat of Corro-tech AP Primer, followed by one stripe coat of Uni-tech UV and one overall coat of Uni-Tech UV.

This system has met all of the clients requirements and they are delighted with the quality of the finish achieved.